

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO ONE	COMMENTS
	<p>AN AERIAL VIEW TAKEN IN JANUARY OF 1993.</p> <p>VIEW IS LOOKING D/S ALONG MURRIETA CREEK TOWARDS ELM STREET.</p> <p>THE FACILITY TO THE RIGHT IS A WATER RECLAMATION PLANT.</p> <p>THE CREEK HAS INUNDATED THE SURROUNDING AREA BY OVERTOPPING THE BANKS</p>
PHOTO TWO	COMMENTS
	<p>JANUARY, 1993 LOOKING DOWNSTREAM AT THE RANCHO CALIFORNIA BOULEVARD BRIDGE.</p> <p>AT THE PEAK OF THE FLOODING, WATER FLOWED OVER THE ROADWAY AND APPROACHES TO THE BRIDGE.</p>

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION **APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT**



PHOTO THREE	COMMENTS
	<p>AN AERIAL VIEW THROUGH OLD TOWNE TEMECULA</p> <p>THE GRANT PROJECT BEGINS AT THE APARTMENT IN THE UPPER LEFT AND CONTINUES DOWNSTREAM</p> <p>NOTE THE SWIMMING POOL FILLED WITH MUD</p> <p>PHOTO FROM JANUARY, '93</p>
PHOTO FOUR	COMMENTS
	<p>FLOOD OF JANUARY 1993.</p> <p>MUDFLOW DAMAGE AT THE U.S. LAND COMPANY IN OLD TOWNE TEMECULA.</p> <p>6th AND FRONT STREET, EAST OF MURRIETA CREEK, JUST U/S OF FIRST PHASE</p>

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO FIVE	COMMENTS
	JANUARY, 1993 4th STREET AND FRONT MARKER SHOWS LEVEL OF MUD INTRUSION
PHOTO SIX	COMMENTS
	JANUARY, 1993 MORE FLOOD DAMAGE MURRIETA CREEK CAN BE SEEN IN THE BACKGROUND

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO SEVEN	COMMENTS
	<p>DOWNSTREAM TERMINUS OF THE PROJECT.</p> <p>THIS SCENE WAS TAKEN PRIOR TO THE 1993 FLOODS</p> <p>COMPARE TO THE DAMAGE PHOTO #8 SHOWING THE</p> <p>SAME VIEW</p>
PHOTO EIGHT	COMMENTS
	<p>JANUARY, 1993</p> <p>SAME VIEWPOINT AS #7 TAKEN IMMEDIATELY AFTER THE FLOODING.</p> <p>PICTURE #9 SHOWS SAME SCENE AFTER CLEANUP EFFORTS</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**
APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO NINE	COMMENTS
	<p>SAME VIEW AS #7-8.</p> <p>THIS SCENE APPROX. ONE YEAR AFTER CLEANUP</p> <p>VEGETATION BEGINS TO RETURN</p>
PHOTO TEN	COMMENTS
	<p>PANORAMIC VIEW OF LOWER REACHES OF FIRST PHASE.</p> <p>TIME FRAME APPROX. 7-92 PRIOR TO 1993 FLOODING</p> <p>COMPARE TO THE FLOOD PICTURE BELOW (#11)</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**
APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO ELEVEN	COMMENTS
	JANUARY, 1993 FLOODING SAME VIEW AS PHOTO #10.
PHOTO TWELVE	COMMENTS
	SAME VIEW AS #11 THIS SCENE APPROX. ONE YEAR AFTER CLEANUP

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**
APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO THIRTEEN	COMMENTS
	PRIOR TO FLOOD DAMAGES LOOKING UPSTREAM AT CONCRETE BATCH PLANT TOWARDS FIRST STREET AND U/S TERMINUS OF PROJECT
PHOTO FOURTEEN	COMMENTS
	JANUARY, 1993 FLOODING SAME VIEW AS PHOTO #13.

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO FIFTEEN	COMMENTS
	<p>SAME VIEW AS #14.</p> <p>TAKEN APPROXIMATELY ONE YEAR AFTER CLEANUP</p>
PHOTO SIXTEEN	COMMENTS
	<p>DECEMBER, 2001</p> <p>LOOKING DOWNSTREAM TOWARDS THE GAGE STA. AND THE LOWER TERMINUS OF PROJECT.</p> <p>NOTE THE SCOURING OF THE INVERT TO BEDROCK.</p> <p>THE SHOPPING CART IN THE FOREGROUND IS TYPICAL OF URBAN STREAMS</p>

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO SEVENTEEN	COMMENTS
	<p>DECEMBER, 2001</p> <p>ON THE EAST B/ THE FIRST STREET BRIDGE.</p> <p>THE SEDIMENT DEPOSITION IS CLEARLY VISIBLE</p> <p>THIS IS THE U/S TERMINUS OF THE FIRST PHASE THIS REACH WILL BE PROTECTED BY GABIONS AS THE PROPERTY IS ALREADY DEVELOPED ON BOTH BANKS</p>
PHOTO EIGHTEEN	COMMENTS
	<p>DECEMBER, 2001</p> <p>JUST UPSTREAM FROM PRIOR PICTURE, MURRIETA CREEK HAS SCOURED THE INVERT.</p> <p>HERE THE FOUNDATIONS OF THE LEFT BANK RECEIVES SEDIMENT.</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO NINETEEN	COMMENTS
 A photograph showing a pile of dry brush and trash along a creek bank. The trash includes a green plastic bottle, a brown paper bag, and other debris. The background shows dense brush and a dirt path.	<p>DECEMBER, 2001</p> <p>TYPICAL TRASH DEPOSITS ALONG THE CREEK</p> <p>IN PARTNERSHIP WITH LOCAL STEWARDS, THE DISTRICT WILL SPONSOR CLEAN UP EFFORTS ALONG THE CREEK AND NEW TRAILSTO BE BUILT ALONG THE BANKS</p>
PHOTO TWENTY	COMMENTS
 A photograph showing trash deposits in a creek stream. The water is murky, and there is a lot of debris, including bottles and plastic refuse, visible in the stream. The background shows a dirt bank and some vegetation.	<p>DECEMBER, 2001</p> <p>TYPICAL TRASH DEPOSITS ALONG THE CREEK BOTTLES AND PLASTIC REFUSE VISIBLE IN STREAM</p> <p>IN PARTNERSHIP WITH LOCAL STEWARDS, THE DISTRICT WILL SPONSOR CLEAN UP EFFORTS ALONG THE CREEK AND NEW TRAILSTO BE BUILT ALONG THE BANKS</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**
APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO TWENTY-ONE	COMMENTS
	<p>DECEMBER, 2001</p> <p>ANOTHER BENEFIT OF THE PROJECT WILL BE THE ELIMINATION OF NON-NATIVE PLANTS COMPETING WITH LOCAL VEGETATION.</p> <p>THIS VIEW SHOWS ARUNDO TAKING HOLD AT THE GAGE STATION, D/S TERMINUS OF THE FIRST PHASE</p>
PHOTO TWENTY-TWO	COMMENTS
	<p>DECEMBER, 2001</p> <p>MORE ARUNDO TAKING HOLD IN THE DOWNSTREAM REACH OF THE FIRST PHASE</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO TWENTY-THREE	COMMENTS
	<p>DECEMBER, 2001</p> <p>THROUGHOUT MURRIETA CREEK, TAMARISK IS RAMPANT.</p> <p>CONSTRUCTION AND THE DISTRICT'S ONGOING PARTNERSHIP WITH THE LOCAL CITIZENS' GROUPS WILL KEEP ARUNDO AND TAMARISK UNDER CONTROL</p>
PHOTO TWENTY-FOUR	COMMENTS
	<p>DECEMBER, 2001</p> <p>BELOW THE GAGE STATION MURRIETA CREEK JOINS TEMECULA CREEK TO FORM THE SANTA MARGARITA RIVER</p> <p>JUST BELOW THIS SCENE IS THE 'GORGE', A WILDLIFE SANCTUARY.</p> <p>THE BEGINNING OF THE GORGE IS REGAINING ITS NATURAL STATE NINE YEARS AFTER THE FLOODING OF 1993. SEE PHOTO #8 TAKEN ABOUT 300 YDS U/S OF THIS SCENE</p>

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO TWENTY-FIVE	COMMENTS
	<p>DECEMBER, 2001</p> <p>THE FIRST OF S POCKET PARKS' TO BE BUILT ALONG MURRIETA CREEK.</p> <p>ALL WILL BE CONNECTED BY BIKE, HIKING OR EQUESTRIAN TRAILS THAT PASS UNDER STREETS</p>
PHOTO TWENTY-SIX	COMMENTS
	<p>DECEMBER, 2001</p> <p>ANOTHER VIEW OF THE PARK IN #25. THIS IS AN EQUESTRIAN PARK WITH PARKING FOR HORSE TRAILERS ALONG DIAZ ROAD</p> <p>THE 'POCKET PARKS' ARE BUT A SINGLE CONCEPT FOR RECREATION AND PUBLIC ACCESS. UPSTREAM A SPORTS PARK OF ABOUT 120 ACRES IS PLANNED AND WILL BE CONTAINED IN A SEDIMENTATION BASIN.</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**
APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT



PHOTO TWENTY-SEVEN	COMMENTS
	<p>DECEMBER, 2001</p> <p>THE PARK IN PHOTOS 25-26 WERE CONSTRUCTED IN COOPERATION WITH A LOCAL CITIZENS' GROUP</p> <p>SUCH PARKS GARNER WIDE SUPPORT IN THE COMMUNITY</p>
PHOTO TWENTY-EIGHT	COMMENTS
	<p>EXISTING CONDITIONS ALONG THE UPPER REACHES OF MURRIETA CREEK</p>

EXHIBIT A**PHOTO SHEETS****MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION**

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT





PHOTO TWENTY-NINE		COMMENTS
		THE LANDSCAPE THE LANDSCAPE ARCHITECT'S CONCEPTUAL VIEW OF MURRIETA CREEK
PHOTO THIRTY		COMMENTS
		AN EXAMPLE OF A HABITAT CORRIDOR ON ONE OF THE DISTRICT'S FACILITIES

EXHIBIT A

PHOTO SHEETS

MURRIETA CREEK, FLOOD PROTECTION CORRIDOR PROGRAM APPLICATION

APPLICANT: RIVERSIDE COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT

PHOTO THIRTY-ONE	COMMENTS
	<p>A VIEW LOOKING THROUGH THE SANTA MARGARITA RIVER GORGE</p>
PHOTO THIRTY-TWO	COMMENTS
	<p>THE WATERSHED OF THE SANTA MARGARITA RIVER</p> <p>NUMBER 1 REPRESENTS MURRIETA CREEK. THE PROJECT SITE IS ABOVE THE CONFLUENCE WITH #8, TEMECULA CREEK.</p>